

Mandatory Product Update/Safety Bulletin

PCU15-013 Safety Bulletin - BMU ONLY (Not in Americas) PC3/Titan Overspeed Safety Device October 30, 2015

COMPLIANCE CATEGORY	PRIORITY CODE
Safety	1
Failure to comply with this product update could result in personal injury or death. Compliance is mandated within a specific operating time.	Prior to unit startup or prior to continued operation (Immediate Action Required)
Compliance Required Identifies the need for action to correct a condition that, if left uncorrected, may result in reduced equipment reliability or efficiency. Compliance may be required within a specific operating time.	2 At first opportunity (Prior to Next Scheduled Maintenance Interval)
Optional Identifies changes that may be beneficial to some, but not necessarily all. Accomplishment at customers discretion.	3 Next Scheduled Maintenance Interval
Notification Customer communication, no action required.	4 Optional / Notification

PRODUCT MODELS AFFECTED							
	PC1 PC3	🛛 Titan	Work	Cages	Platforms	Astro	
	Hoist Accessories	Platform Accessorie	es	Rigg	ing Accessories	Safety Accessories	


COMPONENT SYSTEM						
Electrical	Mechanical	Safety	Other:			

SUB COMPONENT Overspeed Safety Device - Flywheel Assembly

PURPOSE

We have received two reports of Overspeed Safety Device devices failing to trip while performing the routine Daily Test Requirement as referenced in the Power Climber Operators Manual for the PC3/Titan series traction hoist.

Pictures provided from one unit indicate that the flywheel counterweight pins had fallen out or sheared off (see Fig A). If a pin falls out or shears off, the counterweight may get caught on surrounding structure, see Fig B (ex: test push button or mounting bolts). This results in a condition where the flywheel will not trip the overspeed safety trip trigger. In the unlikely event of a loss of traction of the suspension rope in the traction sheave, or a drive train failure leading to a freewheeling traction sheave, the Overspeed Safety Device Cam will not engage and stop motion of the hoist.



The pin non-conformance may not be detected while performing the Daily Test Requirements as outlined in Power Cimper Operators Manual. Additional steps are required to ensure detection of a missing or a sheared pin.

Europe and Asia Pacific +32-3-451.05.00 Service@PowerClimber.be www.PowerClimber.be



Europe and Asia Pacific +32-3-451.05.00 Service@PowerClimber.be www.PowerClimber.be

Power Climber is a division of SafeWorks, LLC. This information is proprietary and may not be copied or distributed without written consent of SafeWorks, LLC.




Mandatory Product Update/Safety Bulletin PCU15-013 Safety Bulletin - BMU ONLY (Not in Americas) PC3/Titan Overspeed Safety Device October 30, 2015

ACTION REQUIRED

PRIOR TO NEXT USE OF HOIST:

 As outlined in the Power Climber Operators Manual, while powering the hoist "UP" and "Down" approximately 3 feet, look through the window near the Overspeed Brake Test Button to view that the flywheel is rotating. If the flywheel is not rotating or stops rotating during operation, hoist must be removed from service immediately.



- 2. If Flywheel Assembly passes inspection, the hoist may be used for up to 120 days as long as the Daily Test Requirements are performed as outlined in Power Climber Operators Manual.
- 3. If the Flywheel Assembly does not pass inspection, hoist must be removed from service until update has been applied.

WITHIN 120 DAYS AN UPDATE MUST BE INSTALLED:

1. A Flywheel Assembly update must be applied, please contact Service@PowerClimber.be or +32 3 451 05 00



Europe and Asia Pacific +32-3-451.05.00 Service@PowerClimber.be www.PowerClimber.be